






Installation order in Red

Don't Touch Components Sorting sheet and installation order

Do not take this sheet,
please leave it on the table

1 and 2 R3 and R4 Brown-Black-Orange-Gold 	3 R2 Brown-Black-Yellow-Gold 	4 R1 Yellow-Purple-Brown-Gold 	5 - 11 R5-11 (7 resistors) Brown-Black-Red-Gold 	12 C1 	13 C2 	14 IC Socket  Note: the notch goes to the left side of the board
Use the lead bending tool to bend the resistor leads to a spacing of 10mm. They can be installed in the board either way round.				This Capacitors can go in either way, and they must be laid down flat on the board.		
15 7 Segment Display  The decimal point must go to the bottom right	16 Switch - Qty 1  The pins must go to the left and right hand side of the board	17 Buzzer  The Pin with the + on it must go on the right hand side of the board	18 Probe 			
19 Brass Loop 	20 Check and test Get your soldering, component placement, and board tested by a leader before going on to the next step Your Leader will help you put in the IC, give you a battery holder and then test the board	21 Battery holder (Remove the cover off the double sided tape before soldering it in)  Ask for the battery once your battery holder is soldered in. 	22 Name, Group and Protective Tape Write your name and group name in the spaces provided on the back, and ask for the protective tape to be put on the board			